

# **CITATION BRAVO 550**

2003 MSN: 550B-1050 REG.NO.: OY-EVO

European Aircraft Sales A/S Lufthavnvej 151, 5270 Odense N Denmark

Telephone: +45 2043 5287

Telephone: +45 4016 5401



### GENERAL INFORMATION

European Aircraft Sales is very happy to announce this Citation Bravo for sale.

The aircraft has a low total time and low engine hours, and is delivered with fresh Phase I-V inspections done!

This Citation Bravo is currently operated on an EU OPS-I AOC, and it has no corrosion and no damage history.

Due to the belted lavatory 8 passenger seats are available in the aircraft, and the range and payload of this aircraft is very good.

Asking price: USD 1,650,000 (ex.VAT)



### **AIRFRAME**

YEAR 2003
TOTAL TIME 5050 hrs
LANDINGS 3685
ZERO FUEL WEIGHT 11,300 lbs
MTOW 14,800 lbs



RANGE 1740 nm



MAX SPEED 400 ktas



MAX PAYLOAD 1925 lbs



SEATS 2+8



LANDING DISTANCE 2517 ft





#### **ENGINES / MAINTENANCE**

Engine type: P&W PW530A

Engine time: 5050 hrs.

Engine No.1 s/n: PCE-DA0512 Engine No. 2 s/n: PCE-DA0513

Engine maintenance plan: Cescom plan.

#### Maintenance notes:

Fresh phase I-V January 2021. New brakes and tires.







### AVIONICS / RADIO

Garmin GTN 750

Garmin GTN 650

Garmin GTX 3000 dual Transponder (ADS-B out)

King KMR-675

King RMT-300

Honeywell Primus 1000

Honeywell p-660

BendixKingTPU67A

Honeywell MKVII

L3 FA2100

Honeywell 980-47-025 SSR

Artex 406af

**EGPWS** 

FDR AlliedSignal

TCAS II

**RVSM** 

CDL

# OTHER EQUIPMENT

- ADI
- HSI Compass system stabilized
- Airspeed Indicator
- Altimeter with Altitude reporting
- Vertical Speed Indicator
- Libelle
- Standby Attitude Indicator
- Standby Altimeter Indicator
- Standby Airspeed Indicator
- Standby Magnetic Compass
- Wing Ice Inspection Lights
- Freon A/C electric
- Oxygen System
- Iridium Sat-phone cockpit + cabin
- Steep approach approved









# **EXTERIOR**

Overall white with blue striping, painted in 2011.



# INTERIOR

Beige leather seats and matching walls. Black carpet and black wood on cupboards and lavatory.

2 pilot seats, 7 passenger seats arranged as one club, one row and a single seat at front. Belted lavatory at the rear of the aircraft.







# CONTACT

For more information, please do not hesitate to contact us.

We look forward to working with you.



